EQUIPMENT NEEDED FOR PURCHASE

| # OF | DOT / | | | | |
|-------|-----------|----------|---------------------------------------------------|-----------------|-------|
| CARS | CLASS | CAPACITY | COMMENTS | PRODUCT | REF# |
| 100 | 111A100W1 | 20,000 | | | 12764 |
| 20 | 111A100W3 | 23,500 | Exterior Coils, Insulated, Top & Bottom Unloading | Plastisizer | 12740 |
| 12 | 111A100W3 | 25,500 | Exterior Coils, Insulated, Top & Bottom Unloading | | 12750 |
| 5 | 111A100W1 | 30,000 | Top & Bottom Unloading, Hazmat Equpped | Ethanol | 12751 |
| 5 | 112J340W | 33,000 | Storage | Refrigerants | 12749 |
| 50-60 | BOX | ANY | Plug Doors, 100 Ton Trucks | | 12712 |
| 30-50 | BOX | 60' | Plate C, 100 Ton Trucks | | 12762 |
| ANY | BOX | 60'-80' | | Lumber | 12672 |
| ANY | FLAT | 60'-80' | Bulkheads | Lumber | 12671 |
| 300 | GONDOLA | 4,680 | Flat Bottom, 100+ Ton Trucks | Waste | 12748 |
| 200 | GONDOLA | ANY | Mill | | 12710 |
| 3-4 | HOPPER | 3,300 | Gravity Gates | | 12702 |
| 50 | LO | 5,200 | | Plastic Pellets | 12722 |
| 50 | LO | 3,800+ | Gravity Gates | | 12683 |
| 50 | LO | 5,750 | Trough Hatches, 110 Ton Trucks | Grain | 12731 |

HAUNTED STATION

Learnington Spa Station in county Warwickshire England was originally built in the late 1800's. It was refurbished in 2008 to restore the Art Deco style of the original builders, the Great Western Railway.

This station is so haunted that the current operators, the Chiltern Railway has hired a supernatural liaison officer. Officer Nick Rees rides with the passengers and acts as a liaison between the railway and all the passengers, including those less substantially composed. His duties are said to include checking ghosts' tickets, ensuring that they do not eat customers' sandwiches, directing them to their train and generally keeping these spooky specters in check. There are signs posted directing ghosts to purchase tickets and prohibiting them from merely "passing through" the gates.

One of the station's more haunted locations is a basement platform with a partially blocked stairwell that seeming leads no where. Staff in the upstairs offices report electrical equipment turning on and off. Drawers are found open with paperwork strewn about. Footsteps are heard when no one else is around. They appreciate the reprieve when meetings abruptly end when doors slam for unknown reasons.

Stephen Herbert, is a night time security officer at the station. He states "I often see and hear ghosts on both platforms but from what I have seen they are nice ghosts and have good energy."

http://metro.co.uk/2014/10/26/train-station-is-so-haunted-they-employ-supernatural-liaison-officer-4921976/
http://www.dailymail.co.uk/travel/travel_news/article-2809468/Leamington-Spa-employs-Supernatural-Liaison-Officer-monitor-train-station-s-ghosts-check-tickets.htm
https://en.wikipedia.org/wiki/Leamington_Spa_railway_station



RAILWAY EQUIPMENT LISTING Published By: TRANSMATRIX, INC.

570 East Higgins Road, Suite 200 Elk Grove Village, IL 60007-1442

PHONE: (847) 228-6022

FAX: (847) 228-6029

October 1, 2015

EQUIPMENT AVAILABLE FOR LEASE

| # OF CARS | DOT / CLASS | CAPACITY | COMMENTS | LAST CONTENTS | REF# |
|--------------|----------------|----------|---------------------------------------------------|-----------------|-------|
| 15-20 | 111A100W1 | 20,800 | | | 12715 |
| 20-30 | 111A100W3 | 23,500 | Exterior Coils, Insulated, Top & Bottom Unloading | Tar Oil | 12746 |
| 50 | AAR211 | 25,300 | Exterior Coils, Insulated Bottom Unloading | Canola Oil | 12739 |
| 100 | 111A100W1 | 30,000 | | Crude Oil | 12717 |
| 2-4 | 111A100W1 | 30,000 | Non-Coiled, Non-Insulated | Crude Oil | 12617 |
| 100 | FLAT | 73' | Center Beam, 110 Ton Trucks | Lumber | 12744 |
| 10 | GONDOLA | 65' | Mill, 5' Sides | Steel | 12768 |
| 10 | GONDOLA | 2,000+ | Mill | | 12713 |
| 45 | GONDOLA | 4,000 | Flat Bottom, 100 Ton Trucks, No Interior Bracing | | 12703 |
| 18 | GONDOLA | 4,000 | Flat Bottom, No Interior Bracing | | 12704 |
| 32 | GONDOLA | 4,170 | Single Tub, No Interior Bracing | | 12705 |
| 29 | GONDOLA | 4,280 | Tub, 1979-80 Built, `100 Ton Trucks | Various | 12766 |
| 110 | HOPPER | 3,800 | Aluminum, Manual Gates, 110 Ton Trucks | Aggregate | 12708 |
| 75 | HOPPER | 3,840 | Steel, Manual Gates, 110 Ton Trucks | | 12707 |
| 20 | LO | 3,000 | Gravity Gates | Sand | 12691 |
| 9 | LO | 3,000 | Round Hatches, 100 Ton Trucks | Sand | 12665 |
| 200 | LO | 4,750 | Trough Hatches, Gravity Gates | Grain | 12730 |
| 140 | LO | 4,750 | Trough Hatches, Gravity Gates | Grain | 12716 |
| 17 | LO | 5,250 | Round Hatches, Pneumatic Gates, 4 Compartment | Plastic Pellets | 12714 |
| 96 | LO | 5,820 | Round Hatches, Pneumatic Gates | Plastic Pellets | 12738 |
| 2 | PD | 5,852 | 1970's Built | Talc | 12727 |

EQUIPMENT NEEDED FOR LEASE

| # OF | # OF DOT/ | | | | | |
|--------------|-------------|-------------|---------------------------------------------------|----------------------------|-------|--|
| CARS | | CAPACITY | COMMENTS | PRODUCT | REF# | |
| | | | | | | |
| 30 | 111A100W2/5 | 13,500 | Rubber Lined | Sulfuric Acid | 12755 | |
| 50 | 111A100W1 | 13,500+ | Insulated, Rubber Lined, Hazmat Equipped | Phosphoric Acid | 12658 | |
| 1-5 | 111A100W1 | 16,000+ | Rubber Lined, Insulated | Ammonium Chloride | 12664 | |
| 3-4 | 111A100W1 | 16,500 | Lined | Caustic Soda | 12663 | |
| ANY | 113A90W3 | 17,000 | Cryogenic | Liquid Argon | 12688 | |
| 2 | 111A100W1 | 20,000 | 2 Compartments, Top & Bottom Unloading | Lube Oil | 12734 | |
| 10-20 | 111A100W1 | 20,000 | | Corn Steep | 12685 | |
| 100 | 111A100W1 | 20,000+ | | | 12764 | |
| 1-10 | 111A100W1/3 | 20,000+ | Exterior Coils, Lined or Ready to Line | Glycol | 12650 | |
| 8 | 111A100W1/3 | 20,000 | Non-coiled, Non-insulated | Ammonium Lignosulfonate | 12613 | |
| 10-20 | 111A100W1/3 | 20,000+ | Exterior Coiled, Insulated | TDI | 12618 | |
| 10-20 | 111A100W3 | 20,000+ | Exterior Coils | Lignin Liquor | 12646 | |
| <i>15-30</i> | 111A100W3 | 21,000 | Exterior Coils, Insulated | Lignin Liquor | 12747 | |
| 2 | 111A100W3 | 21,000 | Exterior Coils, Insulated, Lined | Urea Liquor | 12737 | |
| 2 | 111A100W3 | 21,000+ | Exterior Coils, Insulated | Glycerine | 12699 | |
| 1 | 111A100W1 | 23,500 | Hazmat Equipped | | 12698 | |
| 1-15 | 111A100W1 | 23,500 | | Dicyclopentadiene | 12673 | |
| 20 | 111A100W3 | 23,500 | Exterior Coils, Insulated, Top & Bottom Unloading | Plasticizer | 12740 | |
| 20 | 111A100W3 | 23,500 | Exterior Coils, Insulated, Bottom Unloading | Parrafin Wax | 12641 | |
| 10-20 | 111A100W1 | 25,500 | | Propylene Glycol | 12741 | |
| 5 | 111A100W1 | 26,000 | Top & Bottom Unloading | Lube Oil | 12736 | |
| 15-20 | 111A100W1 | 30,000 | Top & Bottom Unloading | Fuel | 12728 | |
| 50 | вох | 50' | Double Slide Doors, 100 Ton Trucks | | 12627 | |
| 30-50 | вох | <i>60'</i> | | | 12762 | |
| 15-20 | FLAT | 60' | Steel Decks | Steel Bins | 12675 | |
| 20 | FLAT | <i>75</i> ′ | | Lumber | 12742 | |
| 200 | GONDOLA | ANY | Mill | | 12710 | |
| 110 | HOPPER | 2,500+ | | Aggregate | 12656 | |
| 6-8 | HOPPER | 5,000+ | | Corn Starch | 12745 | |
| | | | | | | |

EQUIPMENT NEEDED FOR LEASE

| # OF DOT / CARSCLASS | | CAPACITY COMMENTS | | PRODUCT | REF# |
|-------------------------|----|-------------------|--------------------------------------|------------------|-------|
| 2 | LO | 3,000+ | | Sand | 12662 |
| 200 | LO | 4,750 | Trough Hatches, Gravity Gates | Grain | 12701 |
| 40 | LO | 4,750 | Trough Hatches, Gravity Gates, Lined | Ammonium Nitrate | 12694 |
| 50 | LO | 4,750 | 110 Ton Trucks | Grain | 12767 |
| 50 | LO | 5,750 | Trough Hatches, 110 Ton Trucks | Grain | 12731 |
| 10 | PD | 3,000 | 14.7 PSI | | 12542 |

EQUIPMENT AVAILABLE FOR SALE

| # OF CARS | DOT / CLASS | CAPACITY | COMMENTS | LAST CONTENTS | REF# |
|--------------|----------------|----------|----------------------------------------------|-------------------|-------|
| 100 | 111A100W3 | 23,500 | Exterior Coils, Insulated | | 12719 |
| 100 | 111A100W1 | 30,000 | | Crude Oil | 12717 |
| 150 | 112J340W | 34,500 | | Anhydrous Ammonia | 12752 |
| 25 | BOX | 60' | 100 Ton Trucks, 1968 Built, Extended Service | | 12754 |
| 10 | GONDOLA | 4,000 | 100+ Ton Trucks, Flat Bottom | | 12622 |
| 24 | GONDOLA | 4,240 | | Various | 12266 |
| 110 | GONDOLA | 4,320 | | Coal | 12578 |
| 125 | GONDOLA | 4,520 | 110 Ton Trucks | Coal | 12718 |
| 30 | GONDOLA | 5,277 | Flat Bottom | Waste | 12604 |
| 90+ | HOPPER | 1,970 | Longitudinal Gate | Ore | 12678 |
| 80 | HOPPER | 2,200 | Gravity Gates, 1975-78 Built, 70 Ton Trucks | Ballast | 12753 |
| 7 | HOPPER | 2,100 | Gravity Gates, 70 Ton Trucks | Ballast | 12732 |
| 13 | HOPPER | 2,300 | 60 Degree Slope Sheets, 100 Ton Trucks | Aggregate | 12571 |
| 13 | HOPPER | 3,610 | 4 Pocket, 100 Ton Trucks | | 12624 |
| 75 | HOPPER | 3,840 | Manual Gates | | 12707 |
| 140 | LO | 4,750 | Trough Hatches, Gravity Gates | Sand | 17729 |
| 130 | SCRAP | 85' | 133,000 Light Weight | | 12680 |